

Our Ref: LTR/11034/A/3/AV

Thursday, 2 May 2013

CERTIFICATE

This is to certify that at the request of Energy Matters Pty Ltd, Dome Consulting (Aust) Pty Ltd have reviewed the componentry used in the Sunlock Rooftop Installation Manual Version 4.5 – updated April 2013. In addition Dome Consulting (Aust) Pty has prepared the structural documentation within the Sunlock Rooftop Installation Manual Version 4.5 – updated April 2013.

The check included a review of all regions of Australia wind loading conditions including Cyclonic conditions, in accordance to AS1170.2/Amtdt2/2012.12.24.

The general arrangement of the rails and supports for regions throughout Australia is to comply with the following structural drawings prepared by Dome Consulting (Aust) Pty Ltd which are included in Sunlock Installation Manual Version 4.5:

11034-S1	Rev 00	Dated Mar 2013
11034-S2	Rev 00	Dated Mar 2013
11034-S3	Rev 00	Dated Mar 2013
11034-S4	Rev 00	Dated Mar 2013
11034-S5	Rev 00	Dated Mar 2013
11034-S6	Rev 00	Dated Mar 2013
11034-S7	Rev 00	Dated Mar 2013
11034-S8	Rev 00	Dated Mar 2013
11034-S9	Rev 00	Dated Mar 2013
11034-S10	Rev 00	Dated Mar 2013

The design and documentation has determined that all supporting componentry in the above mentioned documentation was found to be acceptable.

Should you have any further queries please do not hesitate to contact me.

Yours faithfully,
FOR & ON BEHALF OF DOME CONSULTING PTY LTD



Robert Cilia
BE (Civil) RBP RPEQ TBP